

# LEDIZOLV CLEANING METHODS

FOR LEAD DUST REMOVAL



## RAG



+



1/3 CUP

1 GAL

2% SOLUTION



## SPRAY BOTTLE



+



4 TSP.

1 QUART

2% SOLUTION



## MOP



+



1 CUP

3 GAL

2% SOLUTION



## RINSE BUCKET

A SEPARATE BUCKET WITH CLEAN WATER IS NEEDED FOR EACH METHOD. IT IS TO BE USED IN BETWEEN SCRUBBING OR MOPPING.

LEDIZOLV  
CELEBRATING **25** YEARS

888-582-5931

[www.ledizolv.com](http://www.ledizolv.com)

[info@ledizolv.com](mailto:info@ledizolv.com)