

# HOW TO USE LEDIZOLV

## (INDUSTRIAL INSTRUCTIONS)

### PREP STEPS

#### 1 WEAR PROTECTIVE GEAR

Make sure to wear protective equipment and isolate areas with plastic and walk off pads.



#### 2 USE A HEPA VACUUM

Use an industrial strength HEPA vacuum on all surfaces prior to cleaning.



#### 3 PREPARE A 2% SOLUTION

LEDIZOLV	+	WATER
4 tsp.		1 qt.
1/3 cup		1 gal.
1 cup		3 gal.
1 1/2 cup		5 gal.
1 gal.		49 gal.



One gallon of Ledizolv concentrate cleans 10,000 square feet.

# CLEANING METHODS

## THE FLOOR

1. Begin cleaning at one end of the room and work your way to the doorway.
2. Use disposable string mop heads.
3. Mop the floor with a 2% Ledizolv solution.
4. Wring the mop in clean rinse water before repeating.
5. Change and dispose of the mop water when it gets dirty and do a final rinse using fresh water.



## THE WALLS & HORIZONTAL SURFACES

1. Spray down the surfaces with a 2% Ledizolv solution.
2. Wipe with rags, folding the rag to expose clean surfaces for scrubbing.
3. Change rags frequently.
4. Do a final rag rinse of the surface and be sure to wipe and rinse before the surfaces dry out.



## FOR POROUS & HARD-TO-CLEAN SURFACES

1. Use hot water to mix the 2% Ledizolv solution. Scrub surfaces.
2. Allow 5 to 10 minutes for the solution to soak before rinsing.
3. Pre-clean very dirty areas with a heavy duty or degreasing detergent.
4. For lead dust control, surfaces should be smooth and cleanable.
5. Inspect and re-clean surfaces frequently.

